

**GOVERNMENT OF TELANGANA  
ABSTRACT**

Minor Irrigation – Krishna Basin – Siddipet District - “Mission Kakatiya Phase-III” - “Comprehensive Restoration of (18) Minor Irrigation tanks in Siddipet District – Administrative approval for an amount of Rs.350.44 Lakhs - Accorded – Orders - Issued.

---

**IRRIGATION & CAD (MK) DEPARTMENT**

**G.O.Rt.No. 375**

**Dated: 04-04-2017**  
**Read the following:-**

1. From the Chief Engineer, Minor Irrigation (KB), Hyderabad, Lr.No.DCE-I/OT1-AEE5/Mission Kakatiya-III/Siddipet/**List-XIV**/2017, Dt: 07-03-2017.
2. From the Chief Engineer, Minor Irrigation, Hyderabad Lr.No.20193/ DCE-II/ OT1/TO2/Budget/checkslips/2017, Dt.19-01-2017.
3. From the Chief Engineer, Minor Irrigation, Hyderabad, Lr. No. CE/MI/ DCE1/ OT1/AEE5/Finance Department/Remarks/2017, dated: 09-03-2017.

\*\*\*

**ORDER:-**

Government of Telangana has taken-up restoration of all Minor Irrigation Tanks in the State to their original capacity and to effectively utilize water allocated for Minor Irrigation sector under Godavari & Krishna River Basins as a flagship programme under the name of “MISSION KAKATIYA”.

2. The Chief Engineer, Minor Irrigation (KB), Hyderabad in his letter first read above has submitted proposal under Mission Kakatiya Phase-III for “Comprehensive Restoration of (18) Minor Irrigation tanks in Siddipet District for according administrative approval.
3. Government after careful examination of the matter, hereby accord administrative approval for an amount of Rs.3,50,44,000/- (Rupees Three Crores Fifty lakhs and Forty Four Thousand Only) towards “Comprehensive Restoration of (18) Minor Irrigation tanks in Siddipet District for the Financial Year 2017-18 under Mission Kakatiya phase-III Programme, subject to the responsibility of the Chief Engineer, Minor Irrigation (KB), Hyderabad, to follow the following points while giving Technical Sanction and while executing the work. The statement showing the details of tank sanctioned for restoration is annexed to this order:-

- 1) He must ensure and satisfy from the history of repairs carried out to the tanks that there are no overlap of proposed repairs in any other previous sanctioned schemes, now on-going are taken up recently.
- 2) The cost of repairs must be arrived after thorough investigation and as per the actual requirement of components are quantities for restoration and the provisions made including lump sum provisions are in terms of codal provisions and the guidelines issued in relation thereto.
- 3) Whenever applicable, the de-siltation provision made in the estimates are based pre-levels and prudent assessment of quantities involved and in consideration of nature of percolation and potential of the yield.

P.T.O

- 4) Follow due procurement procedures for taking up the works.
- 5) Dismantling of existing damage Structures and construction of new weir and sluice shall be done only in rare cases after due examination of the possibilities of repairs of the existing damage structures at a level not lower than Superintending Engineer.
- 6) Ensure sufficient funds in 2017-18 BE to meet the expenditure towards MK programme works including sanctions considered now before giving technical sanction

4. The expenditure sanctioned in para (3) above shall be debited to the Head of Account "4702 COL on M.I. MH-101-Surface Water GH-11 Normal State Plan SH-(23) – Mission Kakatiya – 530 Major works – 531 Other Expenditure".

5. The Chief Engineer, Minor Irrigation (KB), Hyderabad, shall take necessary action accordingly to complete the work within the stipulated period and submit the utilization certificate to Government. The (18) estimates received through the letter 1<sup>st</sup> read above are returned herewith.

6. This order issues with the concurrence of Finance (EBS.IX) Department vide their U.O. No.3737/25/A2/EBS.IX/2017, Dated:30.03.2017.

**(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)**

**VIKAS RAJ**  
**PRINCIPAL SECRETARY TO GOVERNMENT**

To

The Chief Engineer, Minor Irrigation (KB), Hyderabad (we) (18) original Estimates

**Copy to:-**

The District Collector, Siddipet.

The Accountant General, T.S. Hyderabad.

The Director of Works & Accounts, M.J. Market Road, T.S., Hyderabad.

PS to Hon'ble Minister (Irrgn, Mrkt, and LA)

PS to Principal Secretary to Government, I & CAD Department.

PA to Dy. Secretary to Government (S), I & CAD Department

The Finance (EBS.IX) Department

SF/SCs (C.No.2545/MK/A2//2017).

**//forwarded by order //**

**SECTION OFFICER**

Continued annexure.....

<b>ANNEXURE-I</b> <b>Statement showing the details of tanks sanctioned for Restoration under Mission Kakatiya Phase-III in Siddipet District- List-XIV</b>										
<b>Sl.no</b>	<b>Unique Code</b>	<b>Geo-tagging ID</b>	<b>Name of the Tank</b>	<b>Habitation H/O Village</b>	<b>Mandal</b>	<b>Constituency</b>	<b>Ayacut</b>	<b>Amount Sanctioned for Repairs component Rs in Lakhs</b>	<b>Amount Sanctioned for Desiltation Rs in Lakhs</b>	<b>Total Sanctioned for the work Rs in Lakhs</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>
1	040331700101503	788194182466	Restoration of existing checkdam a/c l/s near Somireddy Narayana well	Jakkapur	Chinnakodur	Siddipet	40.0	8.62	0.00	8.62
2	040331700303323	789292182158	Restoration of existing checkdam a/c l/s near Kamineni Raju well	Mylaram	Chinnakodur	Siddipet	37.0	8.90	0.00	8.90
3	040331700307324	789079182274	Restoration of checkdam a/c l/s near Nallavalla devaiah well	Yellaipally	Chinnakodur	Siddipet	39.0	15.72	0.00	15.72
4	040331701201310	788878182102	Restoration of existing checkdam a/c l/s near Uppala Narsimlu well	Machapur	Chinnakodur	Siddipet	41.0	12.40	0.00	12.40
5	040331701101313	789185181888	Restoration of existing checkdam a/c l/s near Form Society Land	Chinnakodur	Chinnakodur	Siddipet	39.0	9.40	0.00	9.40
6	040331701101314	789185181905	Restoration of existing check dam a/c l/s near Endla Bora vagu	Chinnakodur	Chinnakodur	Siddipet	36.0	10.65	0.00	10.65
7	040331701102308	789082182018	Restoration of existing check dam a/c l/s near Kotha Chinna Rangaiah well	Salandri	Chinnakodur	Siddipet	34.0	11.10	0.00	11.10
8	040331702301309	789060181283	Improvements to Existing checkdam a/c Siddipet vagu, Landa Banda Mathadi	Mandapally	Chinnakodur	Siddipet	40.0	27.96	0.00	27.96
9	040331801301504	790050180429	Alibai checkdam near PWD road	Ankshapur	Nangnoor	Siddipet	35.0	3.58	0.42	4.00

10	040331800701502	789867180736	Check dam at Pedda gudlu	Maqdoompur	Nangnoor	Siddipet	37.0	4.68	0.42	5.10
11	040331700301310	789332182260	Restoration of Feeder channel from Karnalakunta to Jalcheru	Allipur	Chinnakodur	Siddipet	93.0	43.65	0.00	43.65
12	040331701301312	788637181960	Restoration of Pitla Narsaiah Kunta	Gangapur	Chinnakodur	Siddipet	37.0	9.72	0.00	9.72
13	040331702301308	789139181276	Improvements to Navvula Banda Mathadi	Mandapally	Chinnakodur	Siddipet	97.0	24.00	0.00	24.00
14	040411401201302	787372181606	Oora cheru	Hasanmeerapur	Dubbak	Dubbak	67.32	24.45	1.97	26.42
15	040411401101101	787049181535	Chowdari cheru	Peddagundavelly	Dubbak	Dubbak	174.12	42.70	1.22	43.92
16	040411400901311	786789181921	Vepa Kunta	Chillapur	Dubbak	Dubbak	35.0	8.81	1.27	10.08
17	040331800701402	789986180720	Japa Rajaiyah Kunta	Maqdoompur	Nangnoor	Siddipet	37.0	6.98	0.42	7.40
18	040331801401506	790460180617	Construction of two nos. causeway a/c Kanugula vagu (surplus course of Mysamma cheruvu near Nangnoor)	Nangnoor	Nangnoor	Siddipet	315.0	71.40	0.00	71.40
							1233.44	344.73	5.71	350.44

**VIKAS RAJ**  
**PRINCIPAL SECRETARY TO GOVERNMENT**

**//forwarded by order //**

**SECTION OFFICER**